

# **ME3392**

# **ENGINEERING MATERIALS AND METALLURGY**

## UNIT II

## HEAT TREATMENT

**VEERAPANDIAN.K**  
**AP/MECH**



**SEMBODAI RUKMANI VARATHARAJAN ENGINEERING COLLEGE**

# HEAT TREATMENT PROCESS

- **PROPERTIES OF METALS AND ALLOYS  
CHANGED AS DESIRED** HEAT TREATMENT  
PROCESS
- **Controlled heating and cooling** of metals for  
the purpose of **altering their properties.**

## **Purpose of Heat Treatment:**

- To relieve stress created during cold working, welding, casting etc.
- Improve Machinability.
- Change grain size.
- Improve ductility
- Homogenous structure.
- To improve mechanical properties.
- To change the chemical composition.
- To improve magnetic and electrical properties.

# HEAT TREATMENT

- Heat treatment may be defined as an **operation or combination of operations involved heating and cooling** of metals/alloys **to obtain desired properties.**

## STAGES OF HEAT TREATMENT:

1. **Heating** a metal beyond the critical temperature
2. **Holding** a temperature for a sufficient period (time to allow necessary changes)
3. **Cooling** the metal (Quenching) to change nature , size, distribution of micro constituents

# Heat Treatment Processes

1. Annealing
  1. Full annealing
  2. Process annealing
  3. Stress relief annealing
  4. Recrystallisation annealing
  5. Spheroidise annealing
2. Normalizing
3. Hardening

## 4. Tempering

- Austempering
- Martempering

## 5. Case hardening

1. Carburising
2. Nitriding
3. Cyaniding
4. Carbonitriding
5. Flame hardening
6. Induction hardening
7. Flame hardening

# ANNEALING

Annealing is a process of **heating** the steel slightly **above the critical temperature** of steel (723 degrees Centigrade) and allowing it to **cool down very slowly** **furnace it self** .

- STAGES OF ANNEALING:
  - HEATING TO THE DESIRED TEMPERATURE
  - HOLDING OR SOAKING AT THE TEMPERATURE
  - COOLING OR QUENCHING USUALLY AT ROOM TEMPERATURE.




# ANNEALING

ANNEALED METALS



HARDENED METALS



# PURPOSE OF ANNEALING

1. To relieve stresses
2. To induce softness
3. To refine grain size
4. To remove gases

## APPLICATIONS:

1. Casting
2. Forging
3. Press work


# **TYPES OF ANNEALING PROCESS**

- **Full Annealing**
- **Process Annealing**
- **Stress Relief Annealing**
- **Spherodising Annealing**
- **Recrystallisation Annealing**

# FULL ANNEALING


- **Full annealing** is the process of **slowly raising the temperature about 50 °C (90 °F) above the Austenitic temperature** line  $A_3$  or line  $A_{CM}$  in the case of **Hypoeutectoid steels (steels with < 0.77% Carbon)** and 50 °C (90 °F) into the Austenite-Cementite region in the case of **Hypereutectoid steels (steels with > 0.77% Carbon)**.
- It is held at this temperature for sufficient time for all the material to transform into Austenite or Austenite-Cementite as the case may be. It is then slowly cooled at the rate of about 20 °C/hr (36 °F/hr) in a furnace to about 50 °C (90 °F) into the Ferrite-Cementite range. At this point, it can be cooled in room temperature air with natural convection.

# FULL ANNEALING



# Process Annealing

- PURPOSE:
  - It is used to soften and increase the ductility
- Material :
  - Steel wires and sheet products
- OPERATION:
  - Low carbon steels less than 0.25% c heated slightly below the critical temperature
  - It achieve softening and cooled at any desired rate
  - The heating is not like that full annealing
- APPLICATION:
  - Preparing steel sheets and wires of drawing.



# STRESS RELIEF ANNEALING

- **PUROPSE:**

- It is heat treatment process
- Eliminate residual stress induced by casting, quenching, etc

- **CAUSES OF INTERNAL RESIDUAL STRESSES:**

- Plastic deformation
- Non uniform cooling of metal

- **EFFECTS OF INTERNAL RESIDUAL STRESSES:**

- Due to stresses Warpage takes place

- **OPERATION:**

- Heated range 550-650 degree celcius, held for a period of time and cooled slowly.




# RECRYSTALLISATION ANNEALING

- RECRYSTALLATION:
  - Stress **grains are replaced by new, strain free grains** during heating above a **specific minimum temperature**
- RECRYSTALLISATION TEMP:
  - When the recrystallisation takes place(new grains formed) that temp is called recrystallisation temp.
- OPERATION:
  - Cold worked steels are heated to a recrystallisation temp and held for some time, and then cooled
- RESULT:
  - Stress free grains, increase ductility.

## SPHEROIDIZING ANNEALING

- PURPOSE:
  - Medium and **high carbon steels** are having **coarse pearlite** it is too hard for machining.
  - So heat treatment to **develop spheroidite structure**.
  - This structure gives **maximum softness and ductility**
- OPERATION:
  - Prolonged heating **below the critical temperature** then slow cooling
  - Prolonged heating **above and below the critical temp**
  - Holding for several hours followed by slow cooling.



**NORMALISING**

# Normalizing

- It is similar to full annealing.
- **Cooling in air rather than furnace.**
- FULL ANNEALING is expensive and time consuming
- Instead of full annealing, normalising takes place.


## **OBJECTIVES:**

- Refine grainsize
- Increase strength of steel
- Uniform structure
- Relieve of internal stresses

# NORMALISING

- **OPERATION:**

- Heated up to 50-60 degree celcius above critical temperature
- Normalizing contains ferrite and pearlite for hypo eutectoid steels.
- Pearlite and cementite for hyper eutectoid steels.




# DIFFERENCE BETWEEN NORMALISING AND FULL ANNEALING


- Distinguish between annealing & Normalising.  
( At least 4 points 1 Mark for each point – 4 Marks)

ANNEALING	NORMALISING
Main purpose of annealing is to relieve internal stresses	Main purpose of normalizing is to improve mechanical properties of steel.
Less hardness, more T.S. & toughness	Slightly more hardness, less T.S. and toughness
Pearlite is coarse and usually gets	Pearlite is fine and usually appears unresolved with optical microscope
Grain size distribution is more	Grain size distribution is



# SUMMARY OF HEAT TREATMENTS





Annealing, Hardening & Normalising

# QUENCHING

- It's the operation of **rapid cooling** by dipping the hot metal piece **into a quenching bath**.
- The heated steel become much harder and **stronger by a rapid cooling**.



# Quenching Medium

- Cold water
  - 5-10% of CAUSTIC SODA
  - Liquid salt
  - Oil
  - Air
  - 5-20% of NaCl
- 
- **The rate of cooling determines the level of hardness and microstructure of steel**

# STAGES OF QUENCHING

## **1. VAPOUR JACKET STAGE**

- Time of quenching forms a gaseous layer

## **2. VAPOUR TRANSPORT COOLING STAGE**

1. Gaseous layer is not stable
2. Bubbles nucleate

## **3. LIQUID COOLING STAGE**


1. Metals cools below the boiling point
2. Conduction (solid liquid ) takes place.

# Hardening(BY QUENCHING)

- Its a process of **heating the steel above or below the critical temperature** for a particular period and then **allow to cool by oil or water rapidly**

# PURPOSE OF HARDENING

- Hardness of the metal can be **improved to resist wear**
- Cutting ability of the material can **be improved to cut other material**
- **OPERATION:**
  - HEATING
  - SOAKING
  - COOLING





# Factors for getting good hardness

- Carbon content:

when the % **carbon** is less than 0.3% **we cannot do the process, It should be 0.3 – 0.7%C**


- Rate of cooling:

**To get martensite structure we have to cool suddenly**

- SPECIMEN SIZE:

- OTHER FACTORS


- Geometry
- Quenching temp
- Alloying elements





# TEMPERING

- In the **hardening process** we obtained **martensite structure** . In this structure, the material **having brittle property** and also it has **internal stresses**.
- For minimizing the hardness **and removing** the internal stresses we heat the **metal near to upper critical temp once again after quenching** and let it for some time then cool **slowly** by using salt liquid or oil

# CONVENTIONAL QUENCHING AND TEMPERING









Tempering temperature →

(a)



Tempering temperature →

(b)



Tempering temperature →

(c)

# TYPES OF TEMPERING

- Low temperature tempering (150 – 250 ' c)
- Medium temperature tempering (350 – 450 ' c)
- High temperature tempering (500 – 650 ' c)

# INTERRUPTED QUENCHING

- The **rapid cooling** of molten **metal** gives more **problems** like

1. induced stresses
2. distortions (warping)
3. crack formation in steel

In order to overcome the disadvantages a modified quenching is to be followed called interrupted quenching

Two forms of modified Quenching are

**MARTEMPERING**

**AUSTEMPERING**



# MARTEMPERING

(Mar-quenching)

- It's a **interrupted cooling** procedure for a steel to **reduce the stresses**, distortions and cracking of steels that may develop **during rapid quenching**

### Step-1

**Heat the metal** to obtain Austenite structure level

### Step-2


**Quench** the austenite steel in hot oil or molten salt at a temperature **just above the martensite start temp.**

### Step-3

**Hold it** for some time and **stop the treatment before the transformation of austenite to bainite**

### Step-4

**Cool it in a room air.**



# AUSTEMPERING

## (isothermal Quenching)

- It's a isothermal transformation of steel at a temp below that of pearlite formation and above that of martensite transformation
- Its usually used to reduce the quenching distortion and to make a tough and strong steel
- Banite is the structure formed at the end of the process
- ADVANTAGES  
Increased ductility , Toughness and reduced distorsion

## Step-1

**Heat the metal** to austenite temperature

## Step-2

Then quench the steel in a molten salt bath at a temp just **above the martensite start temp** of the steel.



## Step-3

Holding the steel isothermally to **allow the austenite to bainite transformation** to take place

## Step-4

**slow cooling to room temperature in air**

# AUSTEMPERING



TTT DIAGRAM




## WHY – TTT & CCT DIAGRAMS ?


- The phases **martensite and bainite** are **non-equilibrium phase that do not appear in fe-fe<sub>3</sub>c** (iron-iron carbon) phase diagram
- also **strengthening treatment like hardening and tempering are non-equilibrium process.**
- In order to show the influence of varying cooling rates, that is time, on the transformation of austenite other types of diagrams are necessary.
- The time temperature transformation or TTT diagram and the continuous cooling transformation or CCT diagram are used to explain the things in the cooling operation



- **Non-equilibrium cooling** will result in different microstructures hence **altered properties**.
- **TTT diagrams** are the tools that we can use to take into account the **kinetics of the transformation**.
- They show the relationship between time, temperature and (percent) transformation.
- There are two types of TTT diagrams:
  - Isothermal transformation (IT) TTT diagrams
  - continuous cooling transformation (CCT) TTT diagrams

## TIME TEMPERATURE PATH ON ISOTHERMAL TRANSFORMATION DIAGRAM





# PATHS


what transformations happen in:

- a. Path 1 (Red line)
- b. Path 2 (Green line)
- c. Path 3 (Blue line)
- d. Path 4 (Orange line)




## PATH I - (RED)

- a. (Red) The specimen is cooled rapidly to 150 Degree Celcius and let for 20 minutes. The cooling rate is too rapid for pearlite to form at higher temperatures; therefore, the steel remains in the austenitic phase until the  $M_s$  temperature is passed, where [martensite](#) begins to form.
- Since 150 Degree Celcius is the temperature at which half of the austenite transforms to martensite, the direct [quench](#) converts 50% of the structure to martensite.
- Holding at 150 Degree Celcius forms only a small quantity of additional martensite, so the structure can be assumed to be half martensite and half retained austenite.




## PATH 2 - (GREEN LINE)

- b. (Green) The specimen is held at 250 Degree Celcius for 100 seconds, which is not long enough to form bainite.
- Therefore, the second quench from 250 Degree Celcius to room temperature develops a martensitic structure.




## Path 3 – (Blue line)

- c. (Blue) An isothermal hold at 300 Degree Celcius for 500 seconds produces a half-bainite and half-austenite structure.
- Cooling quickly would result in a final structure of martensite and bainite.




## PATH 4 – (Orange Line)

- d. (Orange) Austenite converts completely to **fine pearlite** after **eight seconds** at **600 Degree Celcius** This phase is stable and will not be changed on holding for **100,000 seconds** at **600 Degree Celcius**.
- The final structure obtained while cooling is fine pearlite.






# TTT – MICRO STRUCTURES





# CCT diagram for Fe-C system

- It measure the extent of transformation as a **function of time for a continuously decreasing temperature.**
- Usually materials are cooled continuously, thus **Continuous Cooling Transformation diagrams** are appropriate.
- For continuous cooling, the time required for a reaction to begin and end is delayed, thus the isothermal curves are shifted to longer times and lower temperatures
- **Main difference between TTT and CCT diagrams: no space for bainite in CCT diagram as continuous cooling always results in formation of pearlite.**


The CCT diagram (solid lines) for a 1080 steel compared with the TTT diagram (dashed lines).








+++++ denotes a transformation during cooling





# Superposition of TTT and CCT Diagrams for Eutectoid Steel



HARDENABILITY



# HARDENABILITY

- Hardenability of steel is defines as that property which determines the depth and distribution of hardness induced by quenching by austenite condition.
- **METHOD OF DETERMINING HARDENABILITY :**
  - Jominy end quench test


## JOMINY END QUENCH TEST

- The Jominy end **quench test** is used to **measure the hardenability** of a steel.
- This describes the ability of the steel to be **hardened in depth by quenching**.
- steel to partially or completely **transform from austenite** to some **fraction of martensite** at a given depth below the surface

- High hardenability allows slower quenches to be used (e.g. oil quench), which reduces the distortion and residual stress.
- The test sample is a cylinder with a length of 111.6 mm (4 inches) and a diameter of 25.4 mm (1 inch).



- This is usually at a temperature of 800 to 900°C.
- The test sample is quickly transferred to the test machine,
- where it is held vertically and sprayed with a controlled flow of water onto one end of the sample.
- This cools the specimen from one end,




## Heat Treatment

Unit 5

### Hardenability: Jominy End Quench Test


➤ The most simple and convenient method of determining the Hardenability is the Jominy End Quench Test.





➤ The Jominy test involves heating a standard test piece of diameter 25 mm and length 100 mm to the austenite state, fixing it to a frame in a vertical position and then quenching the lower end by means of a jet of water.

- The hardness is measured at intervals from the quenched end. The interval is typically 1.5 mm for alloy steels and 0.75 mm for carbon steels.
- High hardness occurs where high volume fractions of martensite
- Lower hardness indicates transformation to bainite or ferrite/pearlite microstructures

# Jominy End Quench Test



## Jominy end-quenching test






## Hardness versus distance from the quenched end













[www.pandianprabu.weebly.com](http://www.pandianprabu.weebly.com)

