



## FINITE ELEMENT MODELING AND ANALYSIS OF HOT TURNING OPERATION

## **A PROJECT REPORT**

Submitted by

NAME:

REG NO:

M.AJAYHARIHARAN J.RANJITH S.SIVABALAN A.VENKATESH 821716114301 821716114322 821716114325 821716114328

In partial fulfillment for the award of the degree of

## **BACHELOR OF ENGINEERING**

in MECHANICAL

ENGINEERING

## SIR ISSAC NEWTON COLLEGE OF ENGINEERING AND TECHNOLOGY, PAPPAKOVIL, NAGAPATTINAM-611102

ANNA UNIVERSITY::CHENNAI 600 025

**APRIL 2020** 

#### **BONAFIDE CERTIFICATE**

Certificate that this project report 'FINITE ELEMENT MODELING AND ANALYSIS OF HOT TURNING OPERATION' is the bonafide work of

NAME:

## M.AJAYHARIHARAN J.RANJITH S.SIVABALAN A.VENKATESH

REG NO:

82171611430	)1
82171611432	22
82171611432	25
82171611432	28

Who carried out the project work under my supervision.

## **SIGNATURE**

#### Mr.P.MALAISELVARAJA, M.E.,

#### HEAD OF THE DEPARTMENT,

Department of Mechanical Engineering,

Issac Newton College of

Engineering and Technology,

Pappakovil, Nagapattinam-611102

## **SIGNATURE**

### Mr.A.ARULSAKTHI,M.E.,

#### SUPERVISOR,

Department of Mechanical Engineering Sir Sir Issac Newton College of Engineering and Technology, Pappakovil, Nagapattinam-611102

Submitted for the Anna University Viva- Voce Examination held on \_\_\_\_

## **INTERNEL EXAMINER**

## **EXTERNAL**

## **EXAMINER**

#### ACKNOWLEDGEMENT

At the outset I think the almighty for his showers of blessings and his divine help which enables me to complete the project successfully. First of all I extend my sincere thanks to Mr.T.ANANTH., MBA., chairman, Sir Isaac Newton College of Engineering and Technology, for offering the means of attending my most cherished goal.

I extend my deepest gratitude to **Dr. G.GIFTSON SAMUEL, M.E., Ph.D.,** principal, Sir Isaac Newton college of Engineering and Technology, for giving permission to do the project work successfully.

It gives immense pleasure to extend my sincere and heartful thanks to our head of the department **Mr.P.MALAISELVARAJA.,M.E.,** Assistant professor, Department of Mechanical Engineering, for his encouragement of appreciation, untiring patience, steadfast ,inspiration and valuable help for the successful completion of the project.

I record my sincere and deep sense of gratitude to my project coordinator Mr. P. MALAISELVARAJA., M.E., Assistant professor, Department of Mechanical Engineering and to my supervisor, Mr. A.ARULSAKTHI., ME., Assistant professor, Department of Mechanical Engineering for this guidance and encouragement which has helped me to a lot in completing this project successfully.

I also extend my sincere thanks to staff members of Mechanical Engineering Department.

## **ABSTRACT**

This study examined necessary steps needed be achieve the speed and mileage of an electric vehicles (EVs); pure electric vehicles (PEVs). The development of hybrid cars has greatly reduced the emission level of vehicles. However, this is not enough. The purely electrical vehicles are 100% clean and as such their deployment is of great importance. Therefore, these vehicles replace the internal combustion engine in the conventional cars and automobiles with electric motors. Hence, the need for highly improved motors that can perform optimally is of concern for researchers in the field. In this paper, a review of different electric motors with respect to their design simplicity, cost, ruggedness and efficiency is presented. Finally, the brushless DC motor and lithium-ion batteries are proven to be an efficient and most suitable candidate for propulsion drive in electric vehicles. These all happened just for the need for clean energy and the need to cut carbon dioxide emission from internal combustion engines have led researchers and engineers into exploring and developing new drive systems.

Keywords- EVs, PEVs, BLDC Motor, Lithium-ion Batteries, I.C Engines.

<b>CONTENTS:</b>	<u>PAGE</u> <u>NO</u>
List of Tables:	7
List of Figures:	8
Chapter 1: Introduction	11
<ul><li>1.1 Introduction</li><li>1.2 Hot machining</li><li>1.3 Materials</li><li>1.4 Heating Methods</li><li>1.5 Basic Requirements and Precautions</li></ul>	12 13 14 15 16
Chapter 2: Finite Element Analysis	17
2.1 Introduction	18
2.2 Steps Required	20
Chapter 3: Literature Review	22
Chapter 4: Experimental Setup	26
4.1 Experimental Setup	27
4.2 Workpiece	28
4.3 Tool	29
4.4 Procedure	29
4.5 Observation	31
Chapter 5: Finite Element Modelling and Analysis	33
5.1 Distribution of temperature of workpiece	34
5.2 Modelling of Chip Tool Interface	43
Chapter 6: Results and Discussions	48
<b>Chapter 7: Conclusion and Future Scope</b>	52
References	54

## **List of Tables:**

Table No.	Description	Page No.
3.1	History of cutting processes modelling	24
4.1	Chemical Composition	28
4.2	Mechanical Properties	28
4.3	Physical Properties	28
4.4	Variation of Temperature	31
4.5	Experimental Data	32
5.1	Chemical Composition of workpiece	34
5.2	Work material Properties	34
5.3	Input Parameters	44

## **List of Figures:**

Figure	Description	Page
No.		No.
4.1	Lathe Machine	27
4.2	Workpiece	28
4.3	SNMG Carbide insert	29
4.4	Torch heating the workpiece	30
4.5	Torch withdrawn	30
4.6	Variation of Temp with Distance	31
5.1	3D Model of workpiece	35
5.2	Circular Cross section	36
5.3	Temp Distribution along the Circular CrossSection	36
5.4	Axisymmetric Rectangular Cross section	37
5.5	Temp Distribution	37
5.6	Paths 1, 2 and 3	38
5.7	Paths 4, 5 and 6	38
5.8	Temp Distribution along Path 1	39
5.9	Temp Distribution along Path 2	39
5.10	Temp Distribution along Path 3	39
5.11	Temp Distribution along Path 4	40
5.12	Temp Distribution along Path 5	40
5.13	Temp Distribution along Path 6	40

5.14	Temp Distribution Graph for Path 1	41
5.15	Temp Distribution Graph for Path 2	41
5.16	Temp Distribution Graph for Path 3	41
5.17	Temp Distribution Graph for Path 4	41
5.18	Temp Distribution Graph for Path 5	41
5.19	Temp Distribution Graph for Path 6	41
5.20	Combining Fig 5.14, 5.15 and 5.16	42
5.21	<b>Combining Fig 5.17, 5.18 and 5.19</b>	42
5.22	Chip tool Interface	43
5.23	Chip tool Interface (2D View)	43
5.24	Temperature Distribution at 200°C	45
5.25	Temperature Distribution at 600°C	45
5.26	Effective Strain at 200°C	45
5.27	Effective Strain at 600°C	45
5.28	Effective Stress at 200°C	46
5.29	Effective Stress at 600°C	46
5.30	Tool Wear Rate at 200°C	46
5.31	Tool Wear Rate at 600°C	46
5.32	Cutting Force at 200°C	47
5.33	Cutting Force at 600°C	47
5.34	Thrust Force at 200°C	47
5.35	Thrust Force at 600°C	47

6.1	Temp distribution of workpiece	49
6.2	Variation of temperature with Different Cutting Speed and Temperature	50
6.3	Variation of effective strain with Different Cutting Speed and Temperature	50
6.4	Variation of effective stress with Different Cutting Speed and Temperature	51

# Chapter 1 INTRODUCTION

#### **Chapter 1**

#### **Introduction:**

When the technology of mass production began with the transfer lines from Henry Ford, there came into being the fundamental techniques of working. Any working consumes throughout the world a large amount of money every year. A lot of material is wasted as scrap or chip formation [1]. Using the correct choice of tooling and processing conditions one can use this and greatly reduce processing costs. From the industrial point of view, the most important aspect is the cutting of metal is machinability and its influence on the economy of the process. Machinability has received much attention from researchers. One of the main objectives of the process is the production of materials more economically. A wrong decision can result in expensive production costs and reduces the quality of product [2].

In recent times the manufacturing industries have tried to reduce operating costs while improving the quality. In manufacturing, quality of cutting costs and improving the product are necessary steps to take in an increasingly competitive world, where investors require a higher return on investment. Many manufacturing processes involve some aspects of the operations of cutting, in which there is the need to estimate quantitatively the technological performance of machining operations such as tool life, strength, power and surface finish. This information is necessary for the performance of the selection and design of machine tools and cutting tools, as well as the optimization of cutting conditions for the efficient and effective operations. The most important factor for the successful continuation of production in a typical operation is the wear of cutting tools in metal.

During the last two decades, there has been a considerable industrial interest in the machining of hard to cut. With the advancement of science and technology, there is a need for materials of high hardness and shear strength in the market. The production of exotic materials and intelligent materials has become very essential to meet the strength requirements for the aerospace and defense industry [3]. The production of super alloys and hard materials has become extremely essential to meet the design requirements for critical aerospace and defense industry. The processing of these materials has always been a great challenge for production engineering. These materials are used in the production of components for

electrical, chemical, dental orthopaedics, nuclear and aerospace industries, where high dimensional accuracy, tool life and surface roughness of a satisfactory quality [4]. Components of production beneficial excessive hard materials can be substantial in terms of reduction of processing costs and lead time as compared to the traditional way, which provides for the machining of metals in heat treatment followed by annealing and then the finishing operations, such as grinding operations and polishing, which in turn, consumes a lot of effort, time and work space.

It is also difficult to obtain a good surface finish and tool life while working with materials having high strength, corrosion resistance, toughness, and wear resistance in conventional machining. Processing of these materials requires cutting tools high strength, which is very expensive, and sometimes even impossible. Non-conventional machining process, other practicable means, is mostly limited to low scale removal of material. For the removal of bulk material, the growing interest in the process of hot working is being developed in the industry. In this method, the workpiece is softened by heating and consequently the cutting force is reduced [5].

#### Hot machining:

Tigham first innovated the process of hot machining in 1889, since then it has created much interest among various investigators.

Hot machining operation is a machining method conducted on conventional machine tools in which work piece is preheated before cutting operation to become softer and thereby to reduce its shear strength. The high operating temperature in hot turning process imparts softness on the material under investigation, which eases the machining process and further reduces the high cost of changing and sharpening cutting tools. Softening of the workpiece in hot machining is a more effective method than strengthening the cutting tool in conventional machining [5]. Earlier research has shown that the selection of a proper heating method eliminates the undesirable structural changes in the workpiece and reduces the machining cost. For machining of hard-to-cut steel, the cutting tools materials must be harder than workpiece materials. Due to expensive cost of cutting such materials, the different machining

methods are being used. Usually, formation of second phase particles makes the alloy both stronger and more abrasive and thus more difficult to machine [4]. Advantage, therefore, lies in machining in the soft state.

#### Some remarkable effects of hot machining operation are.

Tool life increases. Cutting forces are less. Less power consumption. Greater productivity due to higher MRR. Strain hardenability and flow stresses in work piece are reduced. Wear and abrasion of cutting tool is less resulting greater tool life. Better surface quality. Hot Machining of brittle ceramic materials is very much easier than any other known approaches.

#### **Materials:**

The materials which are generally machined by hot machining operation are hardened steel, High Manganese steel, NH4 (Ni-hard steel), Superalloys, High Chromium white CI, Ceramic Materials, Hyperchrome CI alloys, Cr-Mo white CI, Stainless Steel, S-816 alloy, X-alloy, Timken 16-25-6, Navy Grade Steel, Inconel-X, Ni-Cr Steel and alloys of tungsten, molybdenum, titanium and tantalum.

### **Heating Methods**

The process of hot working requires the selection of a suitable method for heating. The area or the zone affected by the heat should be as small as possible. The heat should not penetrate very deep within the surface of the material in hot working. At a much higher temperature metallurgical changes occur, then overheating is always undesirable and should be avoided. The various ways of preheating of the workpiece to heat are:

Furnace Heating Resistance Heating Flame Heating (oxy-acetylene, oxy-LPG) Arc Heating Plasma Arc Heating Induction Heating Laser Assisted Heating Radio Frequency Heating Apparatus

#### Basic Requirements and Precautions of Heating the Workpiece:

• Heat applied should be localized in the cutting zone that is just in front of the cutting edge, where the deformation of the workpiece material is maximum.

• Heating should be limited to a small area thus limiting expansion of work piece, so that the dimensional accuracy can be tolerated.

• The method of supply of heat should be such that the limitations imposed by the size and shape of the workpiece, and machining conditions are minimal.

• Machined surfaces must not be contaminated or overheated, resulting in metallurgical changes that can produce distortion to the uncut material.

• The heat source must be able to provide a great contribution to specific heat to create a rapid response to temperature in front of the tool.

• The heating system used must be low initial investment and operation and maintenance.

• Safety should be given priority and is absolutely essential that the method used is not dangerous for the operator.

• The temperature control device must have high degree of accuracy.

Chapter 2 Finite Element Analysis

## Chapter 2

#### **Introduction to Finite Element Analysis:**

Finite Element Analysis (FEA) was developed in 1943 by R. Courant, who used the Ritz method of numerical analysis and minimization of variational calculus to obtain approximate solutions for systems of vibration. Shortly after, an article published in 1956 by MJ Turner, RW Clough, HC Martin, and LJ Topp established a broader definition of numerical analysis. The paper centered on the "stiffness and deformation of complex structures".

FEA consists of a computer model of a material or design that is stressed and analyzed for specific results. It is used in the design of new products, and refinement of the existing product. A company is able to verify a proposed design and will be able to perform the specification of the client before fabrication or construction. Modifying an existing product or structure is used to qualify the product or structure of a new condition of service. In the case of structural failure, FEA may be used to help determine the design modifications to meet the new condition.

There are generally two types of analysis that are used in the industry: 2-D modeling, and 3-D modeling. While 2-D modeling conserves simplicity and allows the analysis to be performed on a relatively normal computer, it tends to give less accurate results. 3-D modeling, however, it produces more accurate results sacrificing the ability to run on all computers faster, but actually [6].

Development of the finite element method (FEM) in the early 1970s pioneered the first simulations of orthogonal machining process. First research work used as a self-development of finite element code. Since 1990 starts massive use of commercial software, which is able to model the process, as NIKE2, ABAQUS / Standard, MARC, ABAQUS / Explicit, deform 2D FLUENT, FORGE 2D, ALGOR, LS DYNA [7].

Finite Element Method (FEM) modeling and simulation of manufacturing processes based is continually attracting researchers to a better understanding of the mechanisms of chip formation, heat generation in the areas of cutting, tool-chip interface friction characteristics and integrity on the machined surfaces. Forecasts of the physical parameters such as temperature and stress distributions play a key role with precision machining processes predictive process engineering. Tool edge geometry is particularly important because it is influence on tool life to achieve more desirable surface integrity is extremely high [8]. Therefore, the development of FEM models based on continuous, accurate and sound characteristic are needed in order to study the influence of the cutting edge geometry, mechanisms of tool wear and cutting conditions on the surface integrity and residual stresses on the machined surfaces.

FEM has some advantages, as it solves problems of contact, bodies of different materials are used, curvilinear region can be approximated by finite elements or described accurately, etc. There are two types of formulations finite elements to describe a continuous medium: Lagrangian and Eulerian.

The Lagrangian is widely used. In an analysis of Lagrange, grid mesh deforms with the material, while in the Eulerian analysis grid is fixed in space. The Lagrangian analysis simulates the entry, exit, stages of intermittent and discontinuous chip formation, while the Eulerian cannot simulate the phases of intermittent and discontinuous chip formation. However, the Eulerian formulation eliminates the need for a chip criteria of division and to avoid distortions of the mesh [9].

In this project work modelling and analysis is done using ANSYS and DEFORM-2D.

## **Steps Required for Modelling and simulating a turning process:**

#### [9]

#### Process setup and conditions:

Before modeling and simulation, the user must set the starting data, i.e. the parameters and process conditions: cutting speed, depth of cut, feed rate, the ambient temperature, if a cooling liquid will be present or not and coefficient of friction. These parameters will be described and set in the first step, pre-processor. When setting the conditions of the process, the user must choose the ambient temperature, coolant with the convection coefficient, friction factor and cutting heat transfer coefficient.

#### Tool and workpiece setup:

For the configuration tool, the user has two options. First, the user can choose the geometry of the tool from the libraries of software tools. Second, if the tool geometry is complex, such as a drill or a milling insert, this can be imported from CAD systems. There should not an area without free edges, no corners are not valid and invalid guidelines.

#### Boundary conditions:

The boundary conditions help the user to determine the interaction of the piece with other objects in the simulation. The boundary conditions are most often used: heat exchange with the environment and the speed in contact between objects in the model, etc.

#### Tool and workpiece material:

A material should be assigned to the tool and another for the piece. The material can be loaded from the library, starting from aluminum and materials beta up to steel and superalloys, including composites. Most of the tools are made of carbide or toilet. If the user requires a special material, the software gives the possibility to create it. The user needs to know some properties of the material.

#### Mesh generation:

FEM uses Lagrangian or Eulerian meshing criteria. The mesh of Lagrange is reformulated in

almost each time step, in order to handle the deformation of the material. If a crash simulation, for any reason, a new simulation can start where the other stopped. The tool and the workpiece meshing are very important for a process simulation accurately. A finer mesh gives a finer granularity. If the number of elements increases, also increases the time. Meshing the piece is much more important. In general, pieces are modeled as objects made of plastic, can be easily deformed and cut by tools. When the mesh deforms, must be frequently regenerated. During the simulation, the mesh helps the reconstruction of distorted material.

#### Simulation controls and database generation:

The end of the pre-processor and also the beginning of the simulation step contain controls simulation and generation of database. The simulation commands, i.e. the number of simulation steps, step size to save, and calculation tool wear are the latest data pre-processing that needs to be set prior to running the simulation.

The tool wear can also be calculated. The structure and properties of the material affect the cutting forces and therefore the rate of wear. Tool-chip interface means first of all cutting parameters, friction, and coolants, these reducing tool wear and cutting temperature if they are set correctly. The instrument must be appropriately chosen for a transaction subject to the FEM modeling and simulation (turning, drilling, and milling). The optimal performance of a tool, a proper combination between the cutting conditions and the properties of the instruments.

# Chapter 3 Literature Review

## **Chapter 3**

#### **Literature Review:**

Studies of metal cutting are as old as more than 100 years. Early research in metal cutting is started with Cocquilhat (1851), which was focused on the work required to remove a given volume of material in drilling [10]. Tresca (1873) first attempted to explain how they are formed chips [11]. Ernest and Merchant (1941) have developed the first model of the simplest and most used for cutting. Lee and Shaffer (1951) [12], Kobayashi and Thomsen (1962) contributed to the study of Ernest and Merchant [13]. Oxley and Welsh (1963) introduced the first model of shear zone with parallel sides of the chip formation process for a predictive theory [14]. Books are the most popular text written by Armerago (1969), Boothroyd (1981), Shaw (1984) and Trent (2000). Knowledge more general introduction can be found at the textbooks written by Kalpakjian, et al. (2006), and DeGarmo, et al. (1997).

**Finite element method** has a wide use in modeling orthogonal (2D) and oblique (3D) metal cutting. Klamecki (1973) has developed one of the first finite element models for metal cutting processes using a Lagrangian elasto-plastic three-dimensional model to date has been limited to the early stages of chip formation [15]. Usui and Shirakashi (1982) have developed the first two-dimensional FE simulation of orthogonal machining using a particular calculation method called iterative method convergence to obtain solutions for the cutting of the steady state [16]. Iwata, et al. (1984) have developed a method for numerical modeling of the shear plane orthogonal to the stationary state on the basis of rigid plastic material model where temperature effects were neglected. Strenkowski and Carroll (1985) developed a numerical model for the orthogonal cut without chip preformed. Their model was based on a large deformation updated Lagrangian code [17]. Komvopoulos and Erpenbeck (1991) introduced a criterion of separation chip using the argument of the tolerance criterion distance to investigate the chip formation [18]. Lin and Lin (1992) have introduced a criterion of the integrated circuit, the residual stresses in the machined surface, the temperature

distribution in the chip, the tool and cutting forces [19]. Ceretti (1996) has developed a model of cutting eliminating elements have reached a critical value of accumulated damage. With the developments of hardware and commercial FE codes, limitations of modeling and computational difficulties have been overcome to some extent, many researchers focused on particular topics of cutting metals [20]. Bil, et al. (2004) compared three codes used in commercial FE simulations of metal cutting 2D, MSC Marc, ThirdWave AdvantEdge and 2D deformation by comparing the experimental results with the simulation results [21]. Özel (2006) and Filice, et al. (2007) [22] used Deform 2D to study the effects of different models of friction on the results of cutting. Attanasio, et al. (2008) included an advanced approach to model heat transfer phenomena tool-chip interface in the numerical simulation to investigate the tool wear by deformation 3D [23]. Davim and Maranhao (2009) used MSC Marc investigate the effects of plastic deformation and plastic strain rate during high speed machining (HSM) [24].

	Analytical Methods	Experimental	Mechanistic and
		Methods	Numerical methods
Before	1941 Martellotti	1944 Kasharin	-
1960	1944 Merchant	1946 Sokalov	
	1956 Dio, Salje	1956 Trigger	
	1958 Tobias		
1960's	1960 Albrecht	1963 Oxley, Zorev	1961 Sabberwal
	1961 Albrecht, Gurney	1964 Pekelharing	1961 Koenigsberger
	1963 Zorev, Trusty	1966 Thomas, Das	
	1969 Kegg	1969 Peters	1962 Sabberwal

 Table 3.1: History of cutting processes modelling [25]

1970's	1974 Hannas, Oto	1970 Knight	1971 Okushima
	1976 Szakovits	1972 Nigm	1973 Klamecki
		1974 Tlusty	1974 Shirakasi, Tay
		1975 Pandit , Baily	1979 Gygax
1980's	1981 Trusty	1981 Komanduri	1980 Lajczok
	1985 Rubenstein	1984 Shi, Shin	1982 Usui
	1986 D.W. Wu	1985 Ahn, et.al	1987 Riddle
	1989 Oxley	1986 Pandit	1988 Carroll
		1987 Ahm	1989 Yang
1990 to			
present	1993 Minis		1992 Yang
	1995 Altintas		1993 Wayne
	1996 Arsecularatne		1994 Athavale
	1998 Waldorf		1995 Shih
	1999 Moufki		1999 Ng et. Al
	2002 Becze, Elbestawi		

# Chapter 4 Experimental Setup

## **Chapter 4**

## **Experimental Setup:**

The experiment was conducted on a central lathe. The following figure (4.1) shows the schematic diagram of a central lathe.



Figure 4.1 Lathe Machine

## Workpiece:

The workpiece comprised of a 500 x 50 mm cylinder made of high manganese steel. The composition, mechanical and physical properties of the high manganese steel work material are given in the following tables.

#### Table 4.1: Chemical Composition

Element	С	Si	Mn	S	Р	Cr	Fe
%age	1.13	0.40	13.0	0.003	<=0.20	1.6	84.23

#### Table 4.2: Mechanical Properties

Brinell Hardness No.	220
Yield Strength	380 MPa
Ultimate Tensile Strength	940 MPa

#### **Table 4.3: Physical Properties**

Density	7.88 g/cc
Expansion coefficient (0°-600°C)	21.5 x 10 <sup>-6</sup> /°C
Specific Heat	502 J/Kg °C
Electrical Resistivity	75 μΩm
Thermal Conductivity	13 W/m °C
Magnetic Permeability	1.002



Figure 4.2 Workpiece

#### **Tool:**

The turning operation was done by SNMG carbide insert.



Fig. 4.3: SNMG Carbide insert

#### **Procedure:**

The workpiece was mounted between the head stock and the tail stock. Heating of the workpiece was done with the help of oxygen + LPG flame. During heating the workpiece was made to rotate constantly so as to avoid localization of heat. Excessive heating may cause change in metallurgical properties of the workpiece material. It may also result in melting of the material.

The experiment must be conducted at particular temperatures for different readings. The temperature of the workpiece must be maintained upto a particular value for a single run. The workpiece must be heated until it reaches the desired temperature. Once it has attained the temperature, heating must be discontinued. Else there will be error in readings.

In this experiment automatic heating arrangement was used. The flame torch was mounted on a shaft which was connected to a servo motor. The actual movement of the torch (mounted on the shaft) facilitated the heating and discontinuation of heating of the workpiece. A thermocouple was used to measure the temperature of the rotating workpiece.

A sensor was attached to the thermocouple which was used to convert the analog signal to digital signal for the servo motor. The display panel displayed the temperature at every instant. The desired temperature was set.



#### Fig. 4.4: Torch heating the workpiece

When the required temperature was attained the torch automatically withdraws and again returns back when the temperature falls thus maintaining a constant temperature.



Fig. 4.5: Torch withdrawn

As a result a steady heat source causing uniform heating was maintained by the LPG flame. The flame affected a region on 10 mm width along the circumference of the workpiece.

## **Observation:**

Heating of the workpiece was done using LPG flame. The temperature of the heat affected zone was maintained using automated heating arrangement.

The following table 4.4 shows the variation of temperature with increasing distance from the heat affected zone when the temperature maintained is 200°C.

Distance from the	0	5	10	25	50	100
source (in mm)						
Temperature in °C	200	162	105	60	37	35

Tab	le	4.	4
Tab	le	4.	4

The variation is shown graphically in the following figure 4.6.



Serial No.	Cutting Speed	Feed S	Depth of cut	Temperature of
	Vc (m/min)	(in mm/rev)	D (in mm)	workpiece (°C)
1	21	.05	.5	200
2	21	.05	.5	600
3	21	.7	.5	200
4	43	.05	.5	200
5	21	.7	.5	600
6	43	.05	.5	600
7	21	.05	1.5	200
8	21	.7	1.5	600
9	43	.7	.5	200
10	21	.7	1.5	200
11	43	.7	.5	600
12	43	.7	1.5	600
13	43	.7	1.5	200
14	21	.05	1.5	600
15	43	.05	1.5	200
16	43	.05	1.5	600

#### Table 4.5: Experimental Data

## **Chapter 5** Finite Element Modelling and

Analysis

## Chapter 5

#### **Distribution of temperature of workpiece:**

(The analysis is performed using ANSYS 14)

#### **Problem Statement:**

A cylindrical workpiece of diameter 50 mm and length of 500 mm is rotated in a turning center at 600 rpm. The workpiece is constantly heated with a heat source in movement which is a flame (LPG + O2). We have to design a model in CFD and do analysis to find out the temperature distribution of the workpiece, tool and chip. The temperature of the workpiece surface in contact with the flame is varied from 200-600°C.

Workpiece material= High manganese steel,

Workpiece length= 500 mm,

Workpiece diameter= 50mm,

Rotational speed N= 600 rpm,

Flame travel= 0.1 mm/rev,

Feed = 0.1 mm/rev.

	Table 5.1 Cher	nical Compositior	n of Workpiece	(High Ma	nganese steel):
--	----------------	-------------------	----------------	----------	-----------------

Metal	Mn	С	Si	Cr	Р	S	Fe
%	12.5	1.2	4	1.6	.058	.01	84.23

#### Table 5.2 Work material properties:

Density (Kg/mm <sup>3</sup> )	Specific heat	Thermal
	(J/Kg-K)	conductivity
		(W/mm-k)
7.8×10 <sup>-6</sup>	$C_p = 420 + 0.67T$	0.05
	Density (Kg/mm <sup>3</sup> ) 7.8×10 <sup>-6</sup>	Density (Kg/mm³)Specific heat (J/Kg-K) $7.8 \times 10^{-6}$ Cp= 420+ 0.67T

## 3D Modelling:

A cylindrical workpiece is modelled in ansys having the following dimensions.

Diameter: 50 mm

Height: 500 mm



Figure 5.1 3D Model of workpiece

In this analysis we assume a uniform heat source of temperature  $500^{\circ}$ C acting along a width of 10 mm along the surface of the workpiece. In the above figure a small circle can be seen (from z=245 mm to z= 255 mm) which is the heat affected region.

Since the heat source is uniform and heat flows uniformly through the workpiece 2D analysis is conducted by taking the following:

Radial cross section (Circular cross section) Axial cross section (Axisymmetric Rectangular cross section)

### Circular cross section:

A circle of radius 50 mm is taken. Material properties of High manganese steel as mentioned above is applied. The surface is meshed by taking element size equal to .25 mm. The element taken is Quad 4 Node 55.



Figure 5.2 Circular Cross section

Initial temperature of the material is 22°C. A temperature of 500°C is applied on the outer surface for 1 second.



Figure 5.3 Temp Distribution along the Circular Cross Section

## Axisymmetric Rectangular Cross section:

A rectangle of dimensions 200 X 25 mm is taken. Material properties of High manganese steel as mentioned above is applied. The surface is meshed by taking element size equal to 1 mm. The element taken is Quad 4 Node 55.

For a symmetric body axisymmetric modelling gives the same result as the 3D model. It is preferred over the 3D model as for the same result computational time required is less. Rotating the axisymmetric planar model about the axis gives the complete 3D model.



Figure 5.4 Axisymmetric Rectangular Cross section

Initial temperature of the material is 22°C. A temperature of 200°C is maintained at the heat affected zone for 60 seconds. The following figure shows the temperature distribution after 60 seconds.



**Figure 5.5 Temp Distribution** 

## Temperature distribution along specific regions using PATHS:

A path is categorized as a form of construction geometry and is represented as a spatial curve to which one can scope path result. The results are evaluated at discrete points along this curve. To analyse the temperature distribution six paths are being created. The centre of the flame is taken as the starting point (0, 0).

**Path 1:** From centre of the flame (0, 0) to x = 100 mm.

**Path 2:** From 15 mm below the surface (0, -15) to x = 100mm (100, -15).

**Path 3:** From 25 mm below the surface (0, -25) to x = 100mm (100, -25) i.e. along the axis.

Path 3 05-05-2013 20:24				<b>ANSYS</b>
A Pam Path 2 Path 3				140
		A-1		A-2
		BI)		B2 62
				Y
	0.00	40.00	88.00 (mm)	×

Fig 5.6: Paths 1, 2 and 3

**Path 4:** From centre of the flame (0, 0) downwards to y = -25 (0, -25).

**Path 5:** From (25, 0) to (25, -25)

**Path 6:** From (50, 0) to (50, -25)



Fig 5.7: Paths 4, 5 and 6

#### Following figures show the temperature distributions:























Fig 5.13: Path 6



The values are obtained from the above analysis and the following graphs are plotted.

Fig 5.18: Path 5

Fig 5.19: Path 6

The following graphs shows the variation of temperature distribution from x = 0 to x = 100 along three different paths (1, 2 and 3) i.e. y = 0, y = -15, y = -25. (Combining first three graphs)



The following graph shows the variation of temperature distribution from y = 0 to y = -25 along three different paths (4, 5 and 6) i.e. x = 0, x = 25, x = 50. (Combining last three graphs)



Combining Fig 5.17, 5.18 and 5.19

## **Modelling of Chip Tool Interface:**

(The analysis is performed using DEFORM-2D)

## Chip Tool Interface:



H = 5 mm

W = 1 mm



Fig 5.23: Chip tool Interface (2D View)

DEFORM 2D was used to model the tool and workpiece. Various input parameters such as cutting velocity, feed and workpiece temperature were taken. The output parameters obtained are given below.

Temperature of chip tool interface Effective strain Effective stress Cutting force Thrust force Tool wear rate

The input parameters were varied shown in the following table 5.3.

	Cutting speed m/min	Feed (mm/rev)	Temperature (°C)
	Fc	S	t
1	21	.05	200
2.	43	.7	600



For the 1 <sup>st</sup> model:	$F_C = 21 \text{ m/min}$
	S = .05  mm/rev
	$T = 200^{\circ}C$

For the 2<sup>nd</sup> model: Fc = 21 m/minS = .05 mm/rev

 $T = 600^{\circ}C$ 

The following figure are obtained for different temperature values i.e. t=200°C and t=600°C.

## Temperature Distribution:





Fig 5.24: 200°C



## Effective Strain:





Fig 5.26: 200°C

Fig 5.27: 600°C

## Effective Stress:



Fig 5.28: 200°C

Stress - Effective (MPa) 1640 1090 547 0.000 Y x

Fig 5.29: 600°C

### Tool Wear Rate:









## Cutting Force:



## Thrust Force:



Fig 5.34: 200°C

Fig 5.35: 600°C

## Chapter 6 Results and Discussions

\_\_\_\_\_

## **Chapter 6**

#### **Temperature distribution of workpiece:**



Here the error arose because the modelling was done by taking the room temperature as 22°C but during the conduction of the experiment the room temperature was above 30°C.



#### **Temperature distribution at the chip tool interface:**

A point is considered at the chip tool interface and its values of temperature, strain and stress are calculated for different values of cutting speed and temperature (feed and depth of cut remaining same).

 $V_C = 21 \text{m/min}, 43 \text{m/min}$ 

 $Temp = 200^{\circ}C, 600^{\circ}C$ 

Feed = .05 mm/rev



It can be seen that the temperature of the chip tool interface increases with increase in cutting speed (Figure 6.2).

## 6.2.3 Effective Strain:



It can be seen that the effective strain decreases with increase in cutting speed, other parameters remaining same. But for a given cutting speed the effective strain increases with increase in temperature of workpiece (figure 6.3).

### **Effective Stress:**



#### Fig 6.4

With increase in temperature the effective stress increases (figure 6.4).

## **Tool Wear Rate and Cutting Forces:**

It can be observed from the figures of tool wear that a minute red region representing high tool wear rate is seen on the model where the temperature of the workpiece is taken to be 200°C. On increasing the temperature to 600°C this region vanishes. Hence it can be concluded that on increasing the temperature of the workpiece the tool wear rate decreases.

Similarly from the figure of Cutting force and thrust force it can be concluded the on increasing the temperature of workpiece the cutting forces decrease.

## Chapter 6 Conclusion and Scope for <u>Future Work</u>

#### Conclusion

The following conclusions can be made:

- The temperature of the chip tool interface increases with increase in cutting speed.
- Effective strain decreases with increase in cutting speed, other parameters remaining same. But for a given cutting speed the effective strain increases with increase in temperature of workpiece
- With increase in temperature the effective stress increases
- On increasing the temperature of the workpiece the tool wear rate decreases.
- On increasing the temperature of workpiece the cutting forces decrease.

Hot machining process can be used for machining hard materials. But there are some shortcomings. The setup with a heating source should be available. Trained personnel should use the flame. Heat should be uniformly distributed throughout the cross section and care should be taken not to overheat the work material as it will change the metallurgical properties.

#### **Future Scope**

- All the experimental values could not be compared.
- The tool for modelling was used from the DEFORM library. In order to get accurate results the tool must be modelled.

## References

[1] Ezugwu, E. O., Key improvements in the machining of difficult-to-cut aerospace superalloys, International Journal of Machine Tools & Manufacture 45 (2005) 1353–1367.

[2] Tosun Nihat, Ozler Latif, A study of tool life in hot machining using artificial neural networks and regression analysis method, Journal of Materials Processing Technology 124 (2002) 99–104.

[3] Maity, K.P., Swain, P.K., An experimental investigation of hot-machining to predict tool life, journal of materials processing technology 198 (2008) 344–349.

[4] Davami, M., Zadshakoyan, M., Investigation of Tool Temperature and Surface Quality in Hot Machining of Hard-to-Cut Materials, World Academy of Science, Engineering and Technology 22 2008.

[5] Ranganathan, S., Senthilvelan, T., Multi-response optimization of machining parameters in hot turning using grey analysis, Int J Adv Manuf Technol (2011) 56:455–462.

[6] www.sv.vt.edu/classes/MSE2094\_NoteBook/97ClassProj/num/widas/history

[7] *Zouhar, J., Piska M.,* Modelling the Orthogonal Machining Process Using Cutting Tools with Different Geometry.

[8] Tugrul Özel and Erol Zeren, Finite Element Method Simulation of Machining of AISI 1045 Steel With A Round Edge Cutting Tool.

[9] Corina et al., 3D FEM Analysis of Cutting Processes, Advances in Visualization, Imaging and Simulation.

[10] Cocquilhat, M. 1851. Experiences Sur La Resistance Utile Produite Dans Le Forage. *Ann. Trav. Publ. En Belgique* 10: 199.

[11] Tresca, H. 1878. On Further Applications of the Flow Solids. *Proc. I. Mech. E. Lond.* 1: 301-345.

[12] Lee, E.H and Shaffer, B.W. 1951. The Theory of Plasticity Applied to a Problem of Machining. *Journal of Applied Mechanics* 18: 405-413.

[13] Kobayashi, S. and Thomsen, E.G. 1962. Metal Cutting Analysis II New Parameters. *Journal of Engineering for Industry* 84: 71-80.

[14] Oxley, P.L.B. and Welsh, M.J.M. 1963. Calculating the Shear Angle in Orthogonal Metal Cutting from Fundamental Stress, Strain, and Strain-rate Properties of the Work piece Material. *Proceedings of the Fourth International Conference on Machine Tool Design and Research Conference* 4: 73-86.

[15] Klamecki, B.E. 1973. Incipient Chip Formation in Metal Cutting- A Three Dimension Finite Element Analysis. *PhD. Thesis*. University of Illinois at Urbana-Champain.

[16] Ushi, E. and Shirakashi, T. 1982. Mechanics of Machining from Descriptive to Predictive Theory. *On the Art of Cutting Metals-* 75 *Years Later* 7: 13-55.

[17] Strenkowski, J.S. and Carroll, J.T. 1985. A Finite Element Model of Orthogonal Metal Cutting. *Trans. ASME J.Eng. Ind.* 107: 349-354.

[18] Komvopoulos, K. and Erpenbeck, S.A. 1991. Finite Element Modeling of Orthogonal Metal Cutting. *Trans. ASME J. Eng. Ind.* 113: 253-267.

[19] Lin, Z.C. and Lin, S.Y. 1992. A Coupled Finite Element Model of Thermo-Elastic-Plastic Large Deformation for Orthogonal Cutting. *Journal of Engineering Materials Technology* 114(2): 31-48.

[20] Ceretti, E., Fallbohmer, P., Wu, W.T. and Altan, T. 1996. Application of 2D FEM to Chip Formation in Orthogonal Metal Cutting. *Journal of Materials and Processing Technology* 59: 169-180.

[21] Bil, H., Kilic, S.E. and Tekkaya, A.E. 2004. A Comparison of Orthogonal Cutting Data from Experiments with Three Different Finite Element Models. *International Journal of Machine Tools and Manufacturing* 44: 933-944.

[22] Filice, L., Micari, F., Rizutti, S. and Umbrello, D. 2007. A Critical Analysis on the Friction Modelling in Orthogonal Machining. *International Journal of Machine Tools and Manufacturing* 47: 709-714.

[23] Attanasio, A., Ceretti, E., Rizzuti, S., Umbrello, D. and Micari, F. 2008. 3D Finite Element Analysis of Tool Wear in Machining. *CIRP Annals Manufacturing* Technology 57: 61-64.

[24] Davim, J.P. and Maranhao, C. 2009. A Study of Plastic Strain and Plastic Strain Rate in Machining of Steel AISI 1045 Using Fem Analysis. *Materials and Design* 30: 160-165.

[25] Mohd Zaim Bin Mohd Zukeri, Study on Cutting Operation in Turning Process By 3D Simulation using DEFORM 3D, eprints.uthm.edu.my/1707/1/MOHD\_ZAIM\_BIN\_MOHD\_ZUKERI